

## A Series 16 A 600 VAC

3 or 4 Contacts + Ground: 10A  
 10, 16 & 32 Contacts + Ground: 16A



Use small blade screwdriver to push wire entry tab in for easy contact removal



**Crimp Tool**

Cat. No.

**WT611TB**

3 or 4 (600 V)	10	16	32
<b>Install to Matching Series Hood/Base</b>			

	3 or 4 + G	10 + G	16 + G	32 + G	
<b>Screw Terminal Inserts</b>					
	<b>Male – Pins</b> 20–14 AWG (0.5–2.5 mm <sup>2</sup> )	MS203A or MS204A (16 AWG max.)	MS210A	MS216A	MS216A+ MS232A
	<b>Female – Sleeves</b> 20–14 AWG (0.5–2.5 mm <sup>2</sup> )	FS103A or FS104A (16 AWG max.)	FS110A	FS116A	FS116A+ FS132A